

MEMORANDUM FOR: All NWS Regional Headquarters, Regional Maintenance Specialists, Electronic Systems Analysts, and Electronics Technicians [Engineering Handbook (EHB)-9 Distribution]

FROM: W/OPS1 - John McNulty

SUBJECT: Transmittal Memorandum for EHB-9, Radiosonde Surface Observing Instrumentation System (RSOIS) Prototype Upgrade Installation for Initial Implementation Sites, Errata Sheet 1, Change to Modification Note 1, Issuance 02-02.

1. Material Transmitted:

Engineering Handbook No. 9 (EHB-9), Aerological Sounding Equipment, Section 3.2, Errata Sheet 1, change to Modification Note 1, Attachment A, Appendix E.

2. Summary:

Errata Sheet No. 1 revises the Base Station Setup, User Menu (U), System Functions Menu (F) command string, listed in Attachment A, Appendix E.

3. Effect on Other Instructions:

Engineering Handbook No. 9 (EHB-9), Aerological Sounding Equipment, Section 1.2, Radiosonde Surface Observing Instrumentation System (RSOIS) Organization Level Maintenance Manual, Attachment A, Appendix E.



## ERRATA 1 TO RSOIS MODIFICATION NOTE 1 (for Electronics Technicians)

Maintenance Branch

W/OPS12: FJZ

Page change to RSOIS Modification Note 1.

**GENERAL:**

This revised page for Attachment A, Appendix E corrects the command string for the Base Station Setup, User Menu (U), System Functions Menu (F) command string, listed at the top of page E-2.

**PROCEDURE:**

Remove and discard Attachment A, Appendix E from EHB-9, Section 3.2, Modification Note 1 and from EHB-9, Section 1.2, *Organization Level Maintenance Manual*. Replace with Attachment A, Appendix E provided with this errata sheet.

**EFFECT ON OTHER INSTRUCTIONS:**

Engineering Handbook No. 9 (EHB-9), Aerological Sounding Equipment, Section 1.2, *Radiosonde Surface Observing Instrumentation System (RSOIS)*, *Organization Level Maintenance Manual*, Attachment A, Appendix E.

**REPORT MAINTENANCE ACTION:**

None.

John McNulty  
Chief, Maintenance, Logistics, and Acquisition Division

EHB-9  
Issuance 02-02  
01/16/02